


CABMATE MODEL: OKTP Oshkosh P-Series (27602200)



ITEM	PART #	DESCRIPTION	QTY	ITEM	PART #	DESCRIPTION	QTY
1	12010054	SHOCK ABSORBER	2	13	1403-1426	7/16 X 3 1/4 UNF HEX CAP SCR (GR 5)	2
2	13020090	AIRLINE-NYLON, 1/4" BULK (FEET)	2.5	14	1403-1430	7/16 X 3 3/4 UNF HEX CAP SCR (GR 5)	2
3	13025203	ELBOW, 1/4 TB 1/8 M-NPT	2	15	1404-1624	1/2 X 3 UNF HEX CAP SCR (GR 8)	1
4	13025497	RUN TEE, 1/4 TB 1/4 PTC, PUSH-IN DOT	1	16	1404-1630	1/2 X 3 3/4 UNF HEX CAP SCR (GR 8)	1
5	13025499	ELBOW-PLUG-IN, 1/4"	1	17	1405-0609	HEX CAP SCREW, M6 X 1 X 45, CLASS 8.8	2
6	13500102	SERVICE KIT-HEIGHT CONTROL VALVE	1	18	1435-1012	5/16 X 1 1/2 UNC RND HD SQ NK BOLT (GR 5)	2
7	15000070	BUMPER-JOUNCE, 1.75	2	19	1476-0607	HEX TOP LOCK NUT, M6 X 1, CLASS 8	2
8	27601015	BRACKET-MOUNT, CROSSMEMBER	1	20	1476-1000	5/16 UNC HEX CTR LOCK NUT (GR B)	2
9	27601016	BRACKET-MOUNT, CAB	1	21	1477-1400	7/16 UNF HEX CTR LOCK NUT (GR B)	4
10	29910052	KIT-LINKAGE, LONG	1	22	1477-1601	1/2 UNF HEX TOP LOCK NUT (GR C)	2
11	29934001	LATERAL CONTROL ROD	1	23	2991-0026	SERVICE KIT-PIVOT BALL	2
12	1102A047	AIR SPRING WITH ATTACHMENTS	2	·			



CABMATE MODEL 27602200




WARNING: FOR SAFETY PURPOSES THE CABMATE MUST BE SUPPLIED FROM A PRESSURE PROTECTED CIRCUIT. IN THE EVENT OF AN AIR LEAK IN THE CAB SUSPENSION, FAILURE TO PROVIDE A PRESSURE PROTECTED CIRCUIT MAY CAUSE LOSS OF AIR PRESSURE TO VITAL SYSTEMS ON THE VEHICLE.




WARNING: LOSS OR APPLICATION OF AIR PRESSSURE TO THE CABMATE WILL CAUSE SUDDEN MOVE-MENT OF THE CAB. PRIOR TO INSTALLING OR PERFROMING ANY MAINTENANCE, BLOCK UP THE CABMATE TO PREVENT THE POSSIBILITY OF INJURY.

HEIGHT ADJUSTMENTS

Measure the design height of the air spring(s). The height should be 5 3/4 inches ± 1/16. To change the height, disconnect one end of the valve linkage and adjust accordingly. Tighten the lock nuts on the valve linkage.





MAINTENANCE

CABMATES need no lubrication and little maintenance. The following components should be checked at the time the truck is being serviced. However, immediate corrective action should be taken if a serious malfunction occurs.

COMPONENT	POSSIBLE PROBLEM	CORRECTIVE ACTION	TORQUE	
Airlines	Air leaks	Replace airline	Compression Nut Hand Tight + 1 Turn	
Fittings	Air leaks	Remove fitting and apply fresh joint compound. Reinstall fitting, but Do Not Overtighten. Do not use teflon tape.	Threaded into: Metal Plastic 15 Hand Tight Ft. Lbs. + 1 Turn	
Air Springs	A. Improper height B. Air leakage	A. Adjust valve linkage to maintain proper air spring height.B. Replace air spring.	Size Metal Plastic 3/8 25 Ft. Lbs 4 Ft. Lbs 1/2 28 Ft. Lbs 10 Ft. Lbs 3/4 30 Ft. Lbs 10 Ft. Lbs	
Height Control Valve	Air spring(s) will not inflate when weight is added to the cab. OR Air springs will not deflate when weight is removed from the cab.	A. Inspect valve to insure drive bearing notch is located on "SUPPLY" port side of valve. If not, loosen lever screw (but do not remove completely) and pull lever loose from drive bearing, rotate drive bearing until the drive bearing notch is in the correct position and resecure lever by tightening lever screw. B. Replace valve.	1/4 Mount Fasteners 10 Ft. Lbs. Bearing Screw 40-50 In. Lbs.	
Shock Absorber	Insufficient dampening effect	Replace shocks	45 Ft. Lbs.	
Lateral Control Rod	A. Loose nuts on lateral control rod bolts B. Worn bushings	A. Tighten securely to clamp the inner sleeve. B. Replace lateral control rod.	40 Ft. Lbs.	

IMPORTANT: Periodically check the tightness of all fasteners.

110425 CV600F